

334 - 500X 1.4 Turbo MultiAir Drivestyle System - Signal invalid B106D-86

			Test results		
1	COMPONENT CONCERNED	CHECK USING DIAGNOSIS EQUIPMENT	OK (NO FAULTS DETECTED)	FAULT DETECTED	OPERATION
	ABS control module	Connect the diagnosis equipment to the vehicle and check for errors in the ABS control module	Go to Step 2	Errors were found in the ABS control module	Continue as instructed by the diagnosis equipment
2	COMPONENT CONCERNED	CHECK USING DIAGNOSIS EQUIPMENT	OK (NO FAULTS DETECTED)	FAULT DETECTED	OPERATION
	Electric steering control unit	Leave the diagnosis equipment connected to the vehicle and check for errors in the power steering control module	Go to Step 3	Errors were found in the power steering control module	Continue as instructed by the diagnosis equipment
3	COMPONENT CONCERNED	CHECK USING DIAGNOSIS EQUIPMENT	OK (NO FAULTS DETECTED)	FAULT DETECTED	OPERATION
	Engine control module	Leave the diagnosis equipment connected to the vehicle and check for errors in the engine control module	Go to Step 4	Errors were found in the engine control module	Continue as instructed by the diagnosis equipment
4	COMPONENT CONCERNED	CHECK USING DIAGNOSIS EQUIPMENT	OK (NO FAULTS DETECTED)	FAULT DETECTED	OPERATION
	Four wheel drive control unit	Leave the diagnosis equipment connected to the vehicle and check for errors in the four-wheel drive control unit	End of diagnosis	Errors were found in the four-wheel drive control unit	Continue as instructed by the diagnosis equipment